



GVR Fitness Equipment Update

1. Canoa Hills Fitness Center

- All equipment functioning properly.

2. Canoa Ranch Fitness Center

- Cybex Arc Trainer Heart rate monitor is inoperable but machine is still functional. Expected repair next week.

3. Desert Hills Fitness Center

- All equipment functioning properly.

4. East Fitness Center

- All equipment functioning properly.

5. Las Campanas Fitness Center

- All equipment functioning properly.

6. Santa Rita Springs Fitness Center

- Abductor (Outer Thigh) machine needs a tertiary frame bolt. Machine is OK to use. Expected repair next week.

Questions? Email Miles@gvrec.org