



GVR Fitness Equipment Update

1. Canoa Hills Fitness Center

- Woodway 38 is in need of drive belt lubrication. OK to use.
- Woodway 41 power cord was sheered in half by treadmill base. New cord is en route.

2. Canoa Ranch Fitness Center

- Cybex Arc Trainer 28 heart rate monitor due for replacement by 4/5/2019.

3. Desert Hills Fitness Center

- The Muscle D Compact Universal is due for replacement with 4 High-End pieces of individual Hoist Fitness pieces on 3/29/2019.

4. East Fitness Center

- None

5. Las Campanas Fitness Center

- True upright bike flywheel requires lubrication. OK to use.

6. Santa Rita Springs Fitness Center

- None

Questions? Email Miles@gvrec.org